03500.014679. JAN 2 5 2006.

C OF C

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re P	atent of:)		
		:	Examiner: H.D. Gibbs	
MAKOTO FUJIMOTO)		
		:	Group Art Unit: 2622	
Appln. No.: 09/631,126)		
Filed: August 2, 2000		:		
riicu.	August 2, 2000	,		- viiooto
For:	LIGHT-SCANNING OPTICAL	,		Certificate
	APPARATUS AND IMAGE	· :		JAN 3 0 2006
	FORMING APPARATUS	.)		
		:		of Correction
U.S. Patent No.: 6,927,883 B1)		
		:		
Issued:	August 9, 2005)	January 24, 2006	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION <u>UNDER RULES 322 AND 323</u>

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

01/26/2006 HALI11 00000005 6927883 01 FC:1811 100.00 GP

FJAN 31 ZUUD

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Lock See Yu-Jahnes

Attorney for Patentee Registration No. 38,667

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801

Facsimile: (212) 218-2200

NY_Main 544429v1

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,927,883 B1

DATED

August 9, 2005

INVENTOR(S) :

MAKOTO FUJIMOTO

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 4, "sense" should read --direction--;

Line 15, "plane" should read --planes--; and

Line 65, "dissolved" should read --resolved--.

COLUMN 3:

Line 2, "to make" should read --which makes--; and

Line 37, "said-first" should read -- said first--.

COLUMN 4:

Line 13, "a" should read -- a--.

COLUMN 5:

Line 44, "cross sectional" should read --cross-sectional--;

Line 47, "cross sectional" should read --cross-sectional--:

Line 59, "cross sectional" should read --cross-sectional--; and

Line 62, "cross sectional" should read --cross-sectional--.

COLUMN 6:

Line 40, "sense" should read --direction--;

Line 42, "so" should be deleted; and

Line 43, "shows" should read --has-- and

"whose-inscribed" should read --whose inscribed--

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY Main 544429v1

PATENT NO. <u>US 6,927,883 B1</u>

No. of add'l. copies @ 30¢ per page

JAN 31 2006

(17 m = 1 500e

Stable Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,927,883 B1

DATED

August 9, 2005

INVENTOR(S) :

MAKOTO FUJIMOTO

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 15, "as" should read --at--;

Line 27, "sense" should read --direction--; and

Line 29, "sense" should read --direction--.

COLUMN 8:

Line 33, "system" should read --system.--.

COLUMN 9:

Line 19, "and the," should read -- and the--; and

Line 33, "Invention" should read --invention--.

COLUMN 10:

Line 42, "cross sectional" should read --cross-sectional--; and

Line 65, "fying" should read --fy--.

COLUMN 12:

Line 15, "where" should read -- \(\text{r':--;} \)

Line 16, "r" should be deleted;

Line 24, "optical," should read --optical--;

Line 32, "on the basis of" should be deleted; and

Line 33, "unit of millimeter" should in --in millimeters--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,927,883 B1</u>

No. of add'l. copies @ 30¢ per page

JAN 31 2006.



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,927,883 B1

DATED

August 9, 2005

INVENTOR(S) :

MAKOTO FUJIMOTO

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 7, "sense" should read --direction--;

Line 10, "shows" should read --has--; and

Line 36, "cylindrical" should read --cylindrical lens--.

COLUMN 15:

Line 6, "cross sectional" should read --cross-sectional--; and Line 30, "cross sectional" should read --cross-sectional--.

COLUMN 16:

Line 7, "affect" should read --affects--;

Line 8, "dissolved" should read --solved--;

Line 55, "where" should read -- r':--

Line 56, "r" should be deleted.

COLUMN 17:

Line 17, "cross sectional" should read --cross-sectional--;

Line 40, "spherical-lens" should read --spherical lens--;

Line 53, "affect" should read --affects--;

Line 56, "dissolving" should read --solving--; and

Line 65, "ea" should read $-\theta$ a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY Main 544429v1

PATENT NO. <u>US 6,927,883 B1</u>

No. of add'l. copies @ 30¢ per page

.

71AN 31 2006

Stable Here Ould! PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,927,883 B1

DATED

August 9, 2005

INVENTOR(S) :

MAKOTO FUJIMOTO

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18:

Line 10, "cross sectional" should read --cross-sectional--;

Line 24, "height-0," should read --height = 0,--; and

Line 50, "an" should read --a--.

COLUMN 20:

Line 51, "an" should read --a--.

COLUMN 22:

Line 42, "an" should read --a--.

COLUMN 23:

Line 29, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 544429v1

PATENT NO. <u>US 6,927,883 B1</u>

"Jini 3 1 2000 per page No. of add'l. copies

2006'

Staple Here Only! BRINTER'S TRING

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,927,883 B1

DATED

August 9, 2005

INVENTOR(S) :

MAKOTO FUJIMOTO

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18:

Line 10, "cross sectional" should read --cross-sectional--;

Line 24, "height-0," should read --height = 0,--; and

Line 50, "an" should read --a--.

COLUMN 20:

Line 51, "an" should read --a--.

COLUMN 22:

Line 42, "an" should read --a--.

COLUMN 23:

Line 29, "an" should read --a--.

NY_MAIN 544429v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,927,883 B1</u>

No. of add'l. copies @ 30¢ per page

7AN 21 2006

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,927,883 B1

DATED

August 9, 2005

INVENTOR(S) :

MAKOTO FUJIMOTO

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 4, "sense" should read --direction--;

Line 15, "plane" should read --planes--; and

Line 65, "dissolved" should read --resolved--.

COLUMN 3:

Line 2, "to make" should read --which makes--; and

Line 37, "said-first" should read --said first--.

COLUMN 4:

Line 13, "a" should read -- a--.

COLUMN 5:

Line 44, "cross sectional" should read --cross-sectional--:

Line 47, "cross sectional" should read --cross-sectional--:

Line 59, "cross sectional" should read --cross-sectional--; and

Line 62, "cross sectional" should read --cross-sectional--.

COLUMN 6:

Line 40, "sense" should read --direction--;

Line 42, "so" should be deleted; and

Line 43, "shows" should read --has-- and

"whose-inscribed" should read --whose inscribed --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY Main 544429v1

PATENT NO. US 6,927,883 B1

No. of add'l. copies @ 30¢ per page



MAN 3 1 2006

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,927,883 B1

DATED

August 9, 2005

INVENTOR(S) :

MAKOTO FUJIMOTO

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 15, "as" should read --at--;

Line 27, "sense" should read --direction--; and

Line 29, "sense" should read --direction--.

COLUMN 8:

Line 33, "system" should read --system.--.

COLUMN 9:

Line 19, "and the," should read -- and the--; and

Line 33, "Invention" should read --invention--.

COLUMN 10:

Line 42, "cross sectional" should read --cross-sectional--; and

Line 65, "fying" should read --fy--.

COLUMN 12:

Line 15, "where" should read -- ¶

Line 16, "r" should be deleted:

Line 24, "optical," should read --optical--;

Line 32, "on the basis of" should be deleted; and

Line 33, "unit of millimeter" should in --in millimeters--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. <u>US 6,927,883 B1</u>

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,927,883 B1

DATED

August 9, 2005

INVENTOR(S) :

MAKOTO FUJIMOTO

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 7, "sense" should read --direction--;

Line 10, "shows" should read --has--; and

Line 36, "cylindrical" should read --cylindrical lens--.

COLUMN 15:

Line 6, "cross sectional" should read --cross-sectional--; and Line 30, "cross sectional" should read --cross-sectional--.

COLUMN 16:

Line 7, "affect" should read --affects--;

Line 8, "dissolved" should read --solved--;

Line 55, "where" should read -- ¶

Line 56, "r" should be deleted.

COLUMN 17:

Line 17, "cross sectional" should read --cross-sectional--;

Line 40, "spherical-lens" should read --spherical lens--;

Line 53, "affect" should read --affects--:

Line 56, "dissolving" should read --solving--; and

Line 65, "ea" should read $-\theta$ a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. _US 6,927,883 B1

No. of add'l. copies @ 30¢ per page



TIAN 31 2006

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,927,883 B1

DATED

August 9, 2005

INVENTOR(S) :

MAKOTO FUJIMOTO

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18:

Line 10, "cross sectional" should read --cross-sectional--;

Line 24, "height-0," should read --height = 0,--; and

Line 50, "an" should read --a--.

COLUMN 20:

Line 51, "an" should read --a--.

COLUMN 22:

Line 42, "an" should read --a--.

COLUMN 23:

Line 29, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,927,883 B1</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) NY_Main 544429v1

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,927,883 B1

DATED

August 9, 2005

INVENTOR(S) :

MAKOTO FUJIMOTO

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18:

Line 10, "cross sectional" should read --cross-sectional--;

Line 24, "height-0," should read --height = 0,--; and

Line 50, "an" should read --a--.

COLUMN 20:

Line 51, "an" should read --a--.

COLUMN 22:

Line 42, "an" should read --a--.

COLUMN 23:

Line 29, "an" should read --a--.

NY_MAIN 544429v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,927,883 B1

No. of add'l. copies @ 30¢ per page

